

Part:	0M-8190C	SUB ASSY FAN 230VAC DUAL SPEED XXW		Reg. No.	0M-8190C-MI
Prepared by:	NNJ	Date:	09.02.2023	Rev. No.	01
Approved by:	SCN	Rev. Date:	09.02.2023	Page:	1 / 1

Rev.	Date	Initials	Remark
1	09.02.2023	NNJ	Initial

Conclusion

The replacement will fit in form and function according to the following checked points.

Seismic	0M-8190C has the same seismic behavior as 0M-8190
EMC	0M-8190C has the same EMC behavior as 0M-8190.
Mechanic	0M-8190C has the same mechanical dimensions and mounting points as 0M-8190.
Electric	The same functionality is provided by 0M-8190C as by 0M-8190
other	N/A

What has changed?

The Fan Speed Control Board XXW has been updated from 0P2441AA to 0P2441AB and the corresponding adapter 0W13746 is added.

Why the change?

The PCB for the Fan Speed Control Board XXW has been updated to increase the creepage between SELV and High Voltage and to improve the PCB routing.

Which part can be replaced by the new part?

0M-8190

What has to be considered with the new part?

The replacement is downward compatible.